

Errata notes

Thank you for buying Hitachi PLC. Following misprinting has been found in the EH-150 application manual version NJI-281H(X). When you are asked by customers about them, please use this errata in order to respond them.

Page	Location	[Wrong]	[Correct]															
4-2	EH-AX8V	8 ch. Current output (0 - 7ch.), 0 to 10 VDC	8 ch. Current input (0 - 7ch.), 0 to 10 VDC															
4-2	EH-AX8H	8 ch. Current output (0 - 7ch.), -10 to 10 VDC	8 ch. Current input (0 - 7ch.), -10 to 10 VDC															
5-142	Function	n=0 to 2 indicates a periodical interrupt scan.	n=0 to 3 indicates a periodical interrupt scan. The cycle time depends on CPU types as below table. <table border="1" data-bbox="1368 655 1888 831"> <thead> <tr> <th></th> <th>CPU104, 208, 308, 316</th> <th>CPUxxxA, 448, 516, 548</th> </tr> </thead> <tbody> <tr> <td>INT 0</td> <td>10 ms</td> <td>5 ms</td> </tr> <tr> <td>INT 1</td> <td>20 ms</td> <td>10 ms</td> </tr> <tr> <td>INT 2</td> <td>40 ms</td> <td>20 ms</td> </tr> <tr> <td>INT 3</td> <td>-</td> <td>40 ms</td> </tr> </tbody> </table>		CPU104, 208, 308, 316	CPUxxxA, 448, 516, 548	INT 0	10 ms	5 ms	INT 1	20 ms	10 ms	INT 2	40 ms	20 ms	INT 3	-	40 ms
	CPU104, 208, 308, 316	CPUxxxA, 448, 516, 548																
INT 0	10 ms	5 ms																
INT 1	20 ms	10 ms																
INT 2	40 ms	20 ms																
INT 3	-	40 ms																